

# Capture Environmental Data with the GAGetrak CyberSensor

CyberSensor is a temperature-humidity monitor that works in combination with GAGetrak and links to your computer via a USB port.

CyberSensor monitors the temperature and relative humidity of your calibration environment, making your calibrations even more precise. Just double-click the Temperature or Humidity field in GAGetrak to populate either with data read from CyberSensor.



## FEATURES

- Accurate temperature and relative humidity monitoring
- USB allows for easy installation
- Provides temperature and humidity information for a specific area
- Receive notification of environmental problems in your monitored area
- Easy to install and set up
- Portable size (2.8" x 2" x 1.25")
- USB cable included

## REQUIREMENTS

- GAGetrak Calibration Management Software
- Pentium 300 MHz computer or faster
- 32 MB RAM or greater
- 1 available USB 1.1 or USB 2 port
- Windows 2000, Windows XP, Vista, Windows 2003 Server
- Internet Explorer 4 or greater
- Web server and Internet connection required for external access

Calibration Entry	
Calibration	Measurements
Gage ID: 022EDigital Caliper 0-6	Description: Caliper 0-6 inch
Gage S/N: SN 13767	Est Costs:
Calb Freq: 30 Days	Costs:
Next Due: 2/5/2004	Hours: 0.0
Calibration Date: 1/6/2004	Time: 11:42:00 AM
Department: QC	Account No:
By: 3791	Certificate No: 0104-000
Calibration Type: Standard	Uncertainty:
Results: Okay to use	Coverage Factor: A
Action Required: None	Deg of Freedom:
As Found Condition: In	Temperature: 71 Deg F
Calibration Status: Passed	Humidity: 12%
Interval Adjustment Method: None	Pressure:
Findings: <input checked="" type="checkbox"/> Pass	Other:
In tolerance	Select Label Design:

MSA Graph Certificate Gage Entry View Label Print Label Edit Label Tape Catalog

Record: 14 of 37

## ACCURACY

Temperature:  $\pm 0.72^{\circ}\text{F}$  ( $41^{\circ}$  to  $104^{\circ}\text{F}$ )  
 $\pm 0.4^{\circ}\text{C}$  ( $5^{\circ}$  to  $40^{\circ}\text{C}$ )

Humidity:  $\pm 2.0\%$  RH (10% to 90% RH)

## OPERATING RANGE

$-40^{\circ}$  to  $125^{\circ}\text{F}$   
 $-40^{\circ}$  to  $51^{\circ}\text{C}$

0% to 100%



1.800.777.7020

www.cybermetrics.com

+001 (480) 922-7300